








HIETAKARI®




8/25 6GRLM


# 713



# Parts




1. x1



2. 6x30 mm  
x4




3. 4.5x45 mm  
x4




4. x4




5. 4.2x13 mm  
x4




6. x1




7. x1




8. x2




9. x2




10. x1




11. x1



12. x5




13. x1




14. x4

# Tools




A




Ø6 mm


B




C




D




E




F




1




2




3




4




5




6




7






8





I.







II.




III.












I.



II.



III.



IV.

