








HIETAKARI®




8/25 6GRLM


713



Parts




1. x1



2. 6x30 mm
x4




3. 4.5x45 mm
x4




4. x4




5. 4.2x13 mm
x4




6. x1




7. x1




8. x2




9. x2




10. x1




11. x1



12. x5




13. x1




14. x4

Tools




A




Ø6 mm


B




C




D




E




F




1




2




3




4




5




6




7






8





I.




II.




III.







I.




II.




III.







I.



II.



III.



IV.

